

# Diagnostic Imaging Systems

- [Radiology Department](#)
  - [Example](#)
  - [X-Ray Machine](#)
  - [CR-Reader](#)
  - [Ultrasound Voluson S6](#)
- [Operating Theatre](#)
- [Emergency Department](#)
- [Intensive Care Unit](#)
- [Outpatient](#)
  - [ECG](#)
  - [Pharmaceutical Refrigerator](#)
  - [Ultrasound Vivid iq](#)
  - [Ultrasound S10 Expert](#)
  - [Ultrasound Voluson S8](#)
  - [Monitoring](#)
  - [Microscope](#)

# Radiology Department

# Example

Operational

Last updated 2026-05-17

Current location —

## Core details

<b>Asset ID</b>	—	<b>Department</b>	—
<b>Device type</b>	—	<b>Location</b>	—
<b>Manufacturer</b>	—	<b>Model</b>	—
<b>Serial number</b>	—	<b>Year</b>	—
<b>Responsible</b>	—	<b>Ownership</b>	Purchase

## Technical

<b>Power</b>	—	<b>Connectivity</b>	—
<b>Other</b>	—		
<b>Software</b>	—		
<b>Consumables</b>	—		

## Maintenance log

PM = Preventive maintenance, CM = Corrective maintenance

Date	Type	Action	By	Ref/Ticket	Next due
—	PM	—	—	—	—

## Notes

Known issues

—

Spare parts on-site

—

Vendor / technician contact

—

Escalation

—

Radiology Department

# X-Ray Machine

Operational

Last updated 2026-05-18

Current location —

## Core details

<b>Asset ID</b>	MT-001	<b>Department</b>	Radiology
<b>Device type</b>	X-Ray Machine	<b>Location</b>	X-Ray Room
<b>Manufacturer</b>	Philips	<b>Model</b>	Optimus 80
<b>Serial number</b>	00.00.025	<b>Year</b>	2001
<b>Responsible</b>	—	<b>Ownership</b>	—

## Technical

<b>Power</b>	230V 3.5A	<b>Connectivity</b>	—
<b>Other</b>	—		
<b>Software</b>	—		
<b>Consumables</b>	—		

## Maintenance log

PM = Preventive maintenance, CM = Corrective maintenance

Date	Type	Action	By	Ref/Ticket	Next due
2024-02-15	PM	Maintainance	EK	—	2025-02-15

## Notes

Known issues

—

Spare parts on-site

—

Vendor / technician contact

—

Escalation

—

Radiology Department

# CR-Reader

Operational

Last updated 2026-05-18

Current location Radiology

## Core details

<b>Asset ID</b>	MT-002	<b>Department</b>	Radiology
<b>Device type</b>	CR Reader	<b>Location</b>	Control room
<b>Manufacturer</b>	Philips	<b>Model</b>	PCR Elva S Plus
<b>Serial number</b>	86827245	<b>Year</b>	2008
<b>Responsible</b>	—	<b>Ownership</b>	Donation

## Technical

<b>Power</b>	100-240V 5A	<b>Connectivity</b>	Network LAN
<b>Other</b>	—		
<b>Software</b>	—		
<b>Consumables</b>	—		

## Maintenance log

PM = Preventive maintenance, CM = Corrective maintenance

Date	Type	Action	By	Ref/Ticket	Next due
—	PM	—	—	—	—

## Notes

Known issues

—

Spare parts on-site

—

Vendor / technician contact

—

Escalation

—

Radiology Department

# Ultrasound Voluson S6

Operational

Last updated 2026-05-18

Current location Radiology

## Core details

<b>Asset ID</b>	MT-003	<b>Department</b>	Radiology
<b>Device type</b>	Ultrasound	<b>Location</b>	Ultrasound Room
<b>Manufacturer</b>	GE	<b>Model</b>	Voluson S6
<b>Serial number</b>	260064SU1	<b>Year</b>	2014
<b>Responsible</b>	—	<b>Ownership</b>	Donation

## Technical

<b>Power</b>	100-240V 900VA	<b>Connectivity</b>	Network LAN
<b>Other</b>	—		
<b>Software</b>	—		
<b>Consumables</b>	—		

## Maintenance log

PM = Preventive maintenance, CM = Corrective maintenance

Date	Type	Action	By	Ref/Ticket	Next due
—	PM	—	—	—	—

## Notes

Known issues

—

Spare parts on-site

—

Vendor / technician contact

—

Escalation

—

# Operating Theatre

# Emergency Department

# Intensive Care Unit

# Outpatient

Outpatient

# ECG

Operational

Last updated 2026-05-18

Current location —

## Core details

<b>Asset ID</b>	MT-004	<b>Department</b>	Outpatient
<b>Device type</b>	Electrocardiograph	<b>Location</b>	Outpatient Cardiology
<b>Manufacturer</b>	Nanjing Kaihong Healthcare Co.Ltd	<b>Model</b>	CNME011224
<b>Serial number</b>	CNME011224-2510053	<b>Year</b>	2025.10
<b>Responsible</b>	—	<b>Ownership</b>	Purchase

## Technical

<b>Power</b>	AC 110-240V 1.5 A DC 14.4V 2200mAh	<b>Connectivity</b>	none
<b>Other</b>	—		
<b>Software</b>	—		
<b>Consumables</b>	—		

## Maintenance log

PM = Preventive maintenance, CM = Corrective maintenance

Date	Type	Action	By	Ref/Ticket	Next due
—	PM	—	—	—	—

## Notes

Known issues

—

Spare parts on-site

—

Vendor / technician contact

—

Escalation

—

Outpatient

# Pharmaceutical Refrigerator

Operational

Last updated 2026-05-18

Current location Outpatient Cardiology

## Core details

<b>Asset ID</b>	MT-005	<b>Department</b>	Outpatient
<b>Device type</b>	Pharmaceutical Refrigerator	<b>Location</b>	Outpatient Cardiology
<b>Manufacturer</b>	Haier Biomedical	<b>Model</b>	HYC-410
<b>Serial number</b>	BE0UK 0E00 0QER2 R0036	<b>Year</b>	2025
<b>Responsible</b>	—	<b>Ownership</b>	Purchase

## Technical

<b>Power</b>	220V-240V 350W	<b>Connectivity</b>	—
<b>Other</b>	—		
<b>Software</b>	—		
<b>Consumables</b>	—		

## Maintenance log

PM = Preventive maintenance, CM = Corrective maintenance

Date	Type	Action	By	Ref/Ticket	Next due
—	PM	—	—	—	—

## Notes

Known issues

—

Spare parts on-site

—

Vendor / technician contact

Qingdao Haier Biomedical Co., Ltd / No. 280 Fengyuan Road, High-tech Zone Qingdao, 266111  
Shandong, P.R. China  
Escalation

—

Outpatient

# Ultrasound Vivid iq

Operational

Last updated 2026-05-18

Current location Outpatient Cardiology

## Core details

<b>Asset ID</b>	MT-006	<b>Department</b>	Outpatient
<b>Device type</b>	Ultrasound	<b>Location</b>	Outpatient Cardiology
<b>Manufacturer</b>	GE	<b>Model</b>	Vivid iq v204
<b>Serial number</b>	6105930WX0	<b>Year</b>	2021
<b>Responsible</b>	—	<b>Ownership</b>	Donation

## Technical

<b>Power</b>	22V 6.8A	<b>Connectivity</b>	Network LAN
<b>Other</b>	—		
<b>Software</b>	—		
<b>Consumables</b>	—		

## Maintenance log

PM = Preventive maintenance, CM = Corrective maintenance

Date	Type	Action	By	Ref/Ticket	Next due
—	PM	—	—	—	—

## Notes

Known issues

—

Spare parts on-site

—

Vendor / technician contact

GE Medical Systems (China) Co.,Ltd, No19. Changjiang Road Wuxi National, Hi-Tech Dev. Zone  
214028 Jiansu, China

Escalation

—

Outpatient

# Ultrasound S10 Expert

Operational

Last updated 2026-05-18

Current location —

## Core details

<b>Asset ID</b>	MT-006	<b>Department</b>	Outpatient
<b>Device type</b>	Ultrasound	<b>Location</b>	Outpatient Gynecology
<b>Manufacturer</b>	GE	<b>Model</b>	Voluson S10 Expert BT18
<b>Serial number</b>	VSX801095	<b>Year</b>	2018
<b>Responsible</b>	—	<b>Ownership</b>	Donation

## Technical

<b>Power</b>	100-240V 900VA	<b>Connectivity</b>	Network LAN
<b>Other</b>	—		
<b>Software</b>	—		
<b>Consumables</b>	—		

## Maintenance log

PM = Preventive maintenance, CM = Corrective maintenance

Date	Type	Action	By	Ref/Ticket	Next due
—	PM	—	—	—	—

## Notes

Known issues

—

Spare parts on-site

—

Vendor / technician contact

GE Ultrasound Korea, Ltd. 9, Sunhwan-ro 214beon-gil, Jungwon-gu Seongnam-si Gyeonggi-do,  
Korea4  
Escalation  
—

Outpatient

# Ultrasound Voluson S8

Operational

Last updated 2026-05-18

Current location Outpatient Gynecology

## Core details

<b>Asset ID</b>	MT-007	<b>Department</b>	Outpatient
<b>Device type</b>	Ultrasound	<b>Location</b>	Outpatient Gynecology
<b>Manufacturer</b>	GE	<b>Model</b>	Voluson S8
<b>Serial number</b>	174121SU4	<b>Year</b>	2012
<b>Responsible</b>	—	<b>Ownership</b>	Donation

## Technical

<b>Power</b>	100-240V 900VA	<b>Connectivity</b>	Network LAN
<b>Other</b>	—		
<b>Software</b>	—		
<b>Consumables</b>	—		

## Maintenance log

PM = Preventive maintenance, CM = Corrective maintenance

Date	Type	Action	By	Ref/Ticket	Next due
—	PM	—	—	—	—

## Notes

Known issues

Connection to Digisono failed

Spare parts on-site

—

Vendor / technician contact

GE Ultrasound Korea Ltd. 65-1 Sangdaewon-dong, Jungwon-gu, Seongnam-si, Gyeonggi-do 462-120  
Korea  
Escalation  
—

Outpatient

# Monitoring

Operational

Last updated 2026-05-18

Current location Outpatient

## Core details

<b>Asset ID</b>	MT-011	<b>Department</b>	Outpatient
<b>Device type</b>	Monitoring	<b>Location</b>	—
<b>Manufacturer</b>	GE	<b>Model</b>	—
<b>Serial number</b>	SH612200169SA	<b>Year</b>	2012
<b>Responsible</b>	—	<b>Ownership</b>	—

## Technical

<b>Power</b>	n/a	<b>Connectivity</b>	none
<b>Other</b>	—		
<b>Software</b>	—		
<b>Consumables</b>	—		

## Maintenance log

PM = Preventive maintenance, CM = Corrective maintenance

Date	Type	Action	By	Ref/Ticket	Next due
— no entries yet —					

## Notes

Known issues

—

Spare parts on-site

—

Vendor / technician contact

Medical System Information Technologies Inc. 8200 West Tower Avenue Milwaukee Wisconsin USA

Escalation

—

Outpatient

# Microscope

Operational

Last updated 2026-05-22

Current location Outpatient

## Core details

<b>Asset ID</b>	MT-66	<b>Department</b>	Gynaecology
<b>Device type</b>	Microscope	<b>Location</b>	Gynaecology
<b>Manufacturer</b>	Leica	<b>Model</b>	020-505.030
<b>Serial number</b>	A20A210054US	<b>Year</b>	n/a
<b>Responsible</b>	—	<b>Ownership</b>	Donation

## Technical

<b>Power</b>	110-250V	<b>Connectivity</b>	none
<b>Other</b>	—		
<b>Software</b>	—		
<b>Consumables</b>	—		

## Maintenance log

PM = Preventive maintenance, CM = Corrective maintenance

Date	Type	Action	By	Ref/Ticket	Next due
— no entries yet —					

## Notes

Known issues

—

Spare parts on-site

—

Vendor / technician contact

—

Escalation

—