

Female Ward

- [Monitoring](#)
- [Suction Pump](#)

Monitoring

Operational

Last updated 2026-05-22

Current location Female Ward

Core details

Asset ID	MT-68	Department	Female Ward
Device type	Monitoring	Location	Nursing Room
Manufacturer	GE	Model	n/a
Serial number	SH612200222SA	Year	2012
Responsible	—	Ownership	Donation

Technical

Power	n/a	Connectivity	none
Other	—		
Software	—		
Consumables	—		

Maintenance log

PM = Preventive maintenance, CM = Corrective maintenance

Date	Type	Action	By	Ref/Ticket	Next due
— no entries yet —					

Notes

Known issues

—

Spare parts on-site

—

Vendor / technician contact

—

Escalation

Suction Pump

Operational

Last updated 2026-05-22

Current location Female Ward

Core details

Asset ID	MT-68	Department	Female Ward
Device type	Suction Pump	Location	Nursing Room
Manufacturer	Medela	Model	03612
Serial number	41707	Year	n/a
Responsible	—	Ownership	Donation

Technical

Power	220V 0.5A	Connectivity	none
Other	—		
Software	—		
Consumables	—		

Maintenance log

PM = Preventive maintenance, CM = Corrective maintenance

Date	Type	Action	By	Ref/Ticket	Next due
2025-02-21	PM	Maintenance	EK	—	—

Notes

Known issues

—

Spare parts on-site

—

Vendor / technician contact

—

Escalation

