

# Monitoring

Operational

Last updated 2026-05-22

Current location Labor Ward

## Core details

<b>Asset ID</b>	MT-67	<b>Department</b>	Labor Ward
<b>Device type</b>	Monitoring	<b>Location</b>	Labor Room
<b>Manufacturer</b>	GE	<b>Model</b>	n/a
<b>Serial number</b>	SDT09310489SP	<b>Year</b>	2009
<b>Responsible</b>	—	<b>Ownership</b>	Donation

## Technical

<b>Power</b>	n/a	<b>Connectivity</b>	none
<b>Other</b>	—		
<b>Software</b>	—		
<b>Consumables</b>	—		

## Maintenance log

PM = Preventive maintenance, CM = Corrective maintenance

Date	Type	Action	By	Ref/Ticket	Next due
— no entries yet —					

## Notes

Known issues

—

Spare parts on-site

—

Vendor / technician contact

—

Escalation

---

Revision #2

Created 2026-05-22 07:55:53 CEST by Admin

Updated 2026-05-22 07:57:15 CEST by Admin