

# Monitoring Monitor 6

Operational

Last updated 2026-05-18

Current location —

## Core details

|                      |                         |                   |           |
|----------------------|-------------------------|-------------------|-----------|
| <b>Asset ID</b>      | MT-012                  | <b>Department</b> | ICU       |
| <b>Device type</b>   | Monitoring              | <b>Location</b>   | ICU       |
| <b>Manufacturer</b>  | Nihon Kohden Coporation | <b>Model</b>      | BSM-2303K |
| <b>Serial number</b> | 00159                   | <b>Year</b>       | 2002      |
| <b>Responsible</b>   | —                       | <b>Ownership</b>  | —         |

## Technical

|                    |     |                     |      |
|--------------------|-----|---------------------|------|
| <b>Power</b>       | n/a | <b>Connectivity</b> | none |
| <b>Other</b>       | —   |                     |      |
| <b>Software</b>    | —   |                     |      |
| <b>Consumables</b> | —   |                     |      |

## Maintenance log

PM = Preventive maintenance, CM = Corrective maintenance

| Date       | Type | Action | By | Ref/Ticket | Next due    |
|------------|------|--------|----|------------|-------------|
| 2024-09-02 | PM   | —      | EK | —          | 42024-12-02 |

## Notes

Known issues

—

Spare parts on-site

—

Vendor / technician contact

—

Escalation

---

Revision #3

Created 2026-05-18 12:28:35 CEST by Admin

Updated 2026-05-18 12:30:48 CEST by Admin